

Technical Newsletter

#tnl2022-0013e

1 / 1



DAD3240 Maintenance Manual Request for Correction of Errors in the Part Number of the Halogen Lamp (Optional Accessory)

Purpose of this Technical Newsletter

We have found some errors in the part number for the halogen lamp (optional accessory) described in the Maintenance Manual for model DAD3240. Please check the details and correct them.

Applicable Maintenance Manual

The object part number is described in Section 1-2 [Replacing the Halogen Lamp (Optional Accessory)] of Chapter F in the Maintenance Manual below.

Applicable model	Part No. of the Maintenance Manual	
DAD3240 equipped with old-type electrical component (Production ID: PE1***)	Japanese	UPESMJH000A, UPESMJH000B
	English	UPESMEH000A, UPESMEH000B

Correction details

Item	Part No. [wrong]	Part No. [correct]
Halogen lamp	DEBDHFS5004-1	DEALMEB5001-1

Inquiries

Please contact your local DISCO sales representative or customer engineer if you have any questions regarding this matter.
